

DIFFICULTY LEVEL

KYMCO CV3 550 '22 - KYMCO CV3 575 '25

K0CV55IF



1 263162 x 1^
263163 x 1

2 260731 x 2
016 011 x 10

3 303045 x 12
08

4 303027X 8
08

5 304172 x 2
M8x70 DIN 7380

fi 260641 x2
016 09 x 22

7 304124 X2
M8x90 DIN912

8 260596 x 4
016 09x20

9 304169X4
M8x50 DIN 7380

10 304174x 2
M8x80 DIN7380

11 260523 x 4
016 09x25

12 304170 x 4
M8x60 DIN 7380

WARNING! A

®> Do not fully tighten the screws until it is ensured that the KIT is correctly attached and aligned. Check tightness every 4 months..



® No apretar los tornillos del todo hasta asegurarse que el KIT esta correctamente colocado y alineado. Repasar apriete cada 4 meses.

© Ziehen Sie die Schrauben nicht ganz fest, bevor Sie sich nicht vergewissert haben, daß der Bausatz korrekt eingestellt und ausgerichtet ist. Alle 4 Monate Drehmoment iiberprufen.


CD Non stringere del tutto le viti fin tanto non si e sicuri che il kit e collocato correttamente e allineato. Controllare il serraggio delle viti ogni 4 mesi..

CD Ne pas serrer les vis avant d'être sûr que le KIT soit correctement positionné et ajusté. Vérifier le serrage des vis tous les 4 mois.


ATTENTION: For a full assembly, mount the 3P System after the Kit Topmaster.






3 x2
MODEL: CV3 550



3* x2
MODEL: CV3 575





K0CV52ST
+
K0CV55IF

